

## MAIR SERVICE BULLETIN

NO. 95 - 10

HURONIA AIRPORT, MIDLAND, ONTARIO, CANADA L4R 4K8 TEL: (705) 526-2871 — FAX: (705) 526-8022

SUBJECT:

Zinc coated steel parts corrosion

AFFECTED MODELS:

Aircraft CH 2000

Serial No. 20-0002; 3; 4; 7; 8 and 9.

COMPLIANCE TIME:

Every 100 Hr. inspection

During the 100 Hr. inspection, all zinc coated (golden-yellow coloured) steel parts must be carefully checked for corrosion.

Where corrosion is starting: clean, degrease and protect with a coat of rustproof paint.